

GLASSTECH REFRACTORY
REFERANSLAR

CUSTOMER	YEAR	WORK	LOCATION	PROJECT
1 TURKMENISTAN FLOAT GLASS FACTORY	2017	Float and container glass refractory lining installation and heat-up	TÜRKMENİSTAN	NEW LINE
2 TURKMENISTAN CONTAINER GLASS FURNACE	2017	Container glass furnace refractory lining installation, hot repair and hot sealing services	TURKMENISTAN	NEW LINE
3 GUROK -LAV A FIRINI	2017	Table ware glass furnace deconstruction , construction and heat-up	TURKEY	COLD REPAIR/REFRACTORY RECYCLING
4 DUZCE CAM FLOAT FURNACE 2	2016	Float glass furnace and tin bath refractory lining installation and heat	TURKEY	NEW FLOAT LINE
5 PASABAHCE MERSIN (SISECAM)	2016	Table ware glass furnace hot repair	TURKEY	HOTREPAIR
6 PASABAHCE ESKISEHIR FURNACE A (SISECAM)	2016	Table ware glass hot repair - LEGRIT	TURKEY	HOTREPAIR
ANDOLU CAM MERSIN F20 FURNACE	2016	Application of regenerator	TURKEY	REFRACTORY RECYCLING
7 (SISECAM)	2016	Container glass furnace refractory deconstruction and refractory	TURKEY	REFRACTORY RECYCLING
8 BUSKI WASTE INCINERATION FURNACE	2016	bed fluid incineration and gas channel refractory lining installation	TURKEY	NEW LINE
9 TRAKYA CAM TR4 FURNACE (SISECAM)	2015	Float glass furnace and tin bath refractory deconstruction, refractory lining installation, heat-up services	TURKEY	COLD REPAIR / REFRACTORY RECYCLING
10 VIDROPORTO GLASS BRASIL (HORN)	2014	Container glass furnace steel structural fabrication	BRASIL	NEW LINE
11 TRAKYA GLASS RUSCAM (SISECAM)	2014	Float glass furnace and tin bath refractory lining installation and heat	RUSSIA	NEW FLOAT LINE
12 TRAKYA GLASS BULGARIA (SISECAM)	2014	Float glass furnace and tin bath refractory lining installation and heat	BULGARIA	NEW FLOAT LINE
13 TRAKYA GLASS BULGARIA (SISECAM)	2014	Container glass furnace refractory lining installation and heat -up	BULGARIA	NEW LINE
14 TRAKYA GLASS BULGARIA (SISECAM)	2014	Tablewareglass furnace refractory deconstruction , refractory lining installation , heat- up services	BULGARIA	COLD REPAIR
ANADOLU CAM GEORGIEN MINA FACTORY	2014	Container glass furnace refractory deconstruction , refractory lining installation and heat-up services	GEORGIEN	COLD REPAIR
15 (SISECAM)	2014	Hand made glass furnace refractory deconstruction, refractory lining	TURKEY	COLD REPAIR
16 DENIZLI CAM (SISECAM)	2014	Installation and heat-up services	TURKEY	COLD REPAIR
17 GURAL CAM LAV	2014	Tableware furnace refractory deconstruction, refractory lining installation ,heat -up services	TURKEY	COLD REPAIR
18 PARKCAM CINER	2013	Container glass furnace refractory lining installation and heat up services	TURKEY	NEW LINE
19 NAMPAK GLASS SOUTH AFRICA(HORN)	2013	Container glass furnace steel structural fabrication	SOUTH AFRICA	NEW LINE
20 ANADOLU CAM MERSIN (SISECAM)	2013	Container glass furnace refractory deconstruction, refractory lining installation and heat-up	TURKEY	COLD REPAIR/REFRACTORY RECYCLING
TRAKYA CAM LULEBURGAZ TR2 FURNACE (	2012	Float glass furnace and tin bath refractory deconstruction, refractory lining installation and heat-up services	TURKEY	COLD REPAIR
21 SISECAM)	2012	Container glass furnace refractory lining installation, steel structure	GEORGIEN	NEW LINE
ANADOLU CAM GEORGIEN MINA FACTORY	2012	Fabrication and erection, heat up services	TURKEY	NEW LINE
22 (SISECAM)	2012	Container glass furnace refractory deconstruction, refractory lining installation and heat-up	TURKEY	NEW LINE
23 ANADOLU CAM ESKISEHIR	2012	Float glass furnace steel structural fabrication	DAGHESTAN	NEW LINE
24 CASPIAN FLOAT GLASS DAGHESTAN(HORN)	2011	Annual furnace maintenance contract	TURKEY	HOT
25 ANADOLU CAM TOPKAPI FACTORY (SISECAM)	2011	Tableware glass furnace refractory deconstruction, refractory lining installation and heat-up	TURKEY	COLD REPAIR
26 PASABAHCE ESKISEHIR FURNACE B (SISECAM)	2011	Tableware glass furnace refractory deconstruction, refractory lining installation and heat-up	TURKEY	COLD REPAIR
27 PASABAHCE MERSIN FURNACE B (SISECAM)	2011	Tableware glass furnace refractory deconstruction, refractory lining installation and heat-up	TURKEY	COLD REPAIR
PASABAHCE KIRKLARELI FURNACE C (	2011	Tableware glass furnace refractory deconstruction, refractory lining installation and heat-up	TURKEY	COLD REPAIR
28 SISECAM)	2011	Tableware glass furnace refractory deconstruction, refractory lining installation and heat-up	TURKEY	COLD REPAIR
PASABAHCE KIRKLARELI FURNACE E (	2011	Tableware glass furnace refractory deconstruction, refractory lining installation and heat-up	TURKEY	COLD REPAIR
29 SISECAM)	2011	Float glass furnace and tin bath refractory deconstruction, refractory lining installation and heap up services	TURKEY	COLD REPAIR/REFRACTORY RECYCLING
TRAKYA CAM LULEBURGAZ TR1 FURNACE (	2010	Refractory deconstruction, refractory lining installation and heap up services	TURKEY	COLD REPAIR/REFRACTORY RECYCLING
30 SISECAM)	2010			

GLASSTECH REFRACTORY
REFERANSLAR

CUSTOMER	YEAR	WORK	LOCATION	PROJECT
		TABLEWARE FURNACE REFRACTORY DECONSTRUCTION, REFRACTORY LINING INSTALLATION ,HEAT -UP SERVICES		COLD REPAIR/REFRACTORY RECYCLING
31 PASABAHCE KIRKLARELI FURNACE D ANADOLU CAM MERSIN FURNACE 20 32 (SISECAM)	2010		TURKEY	
33 GURALLAR YAPI TRAKYA CAM LULEBURGAZ TR2 FURNACE (	2010	CONTAINER GLASS FURNACE HOT REPAIR CONTAINER GLASS FURNACE REFRACTORY LINING INSTALLATION AND HEAT-UP SERVICES	TURKEY	HOT REPAIR NEW LINE
34 SISECAM)	2010		TURKEY	
35 DUZCE CAM FLOAT FURNACE 1	2009	FLOAT GLASS FURNACE REFRACTORY HOT REPAIR FLOAT GLASS FURNACE AND TIN BATH INSTALLATION, HEAT UP SERVICES	TURKEY	HOT REPAIR NEW LINE
36 GUROK ARTCRAFT FURNACE A	2009	TABLEWARE GLASS FURNACE REFRACTORY DECONSTRUCTION ,REFRACTORY LINING INSTALLATION AND HEAT UP	TURKEY	COLD REPAIR
ANADOLU CAM TOPKAPI FURNACE 37 A(SISECAM)	2009	CONTAINER GLASS FURNACE REFRACTORY DECONSTRUCTION, REFRACTORY LINING INSTALLATION AND HEAT -UP	TURKEY	COLD REPAIR
ESKİSEHIR PASABAHCE FURNACE A (		TABLEWARE GLASS FURNACE REFRACTORY		
38 SISECAM)	2008	LINING INSTALLATION AND HEAT-UP FLOAT GLASS FURNACE AND TIN BATH	TURKEY	COLD REPAIR
TRAKYA CAM MERSIN TR3 FURNACE(		REFRACTORY DECONSTRUCTION, REFRACTORY		COLD REPAIR /
39 SISECAM)	2008	LINING INSTALLATION AND HEAT UP SERVICES CONTAINER GLASS FURNACE REFRACTORY	TURKEY	REFRACTORY RECYCLING
40 SISECAM BURSA YENİSEHIR FURNACE B	2007	LINING INSTALLATION AND HEAT -UP CONTAINER GLASS FURNACE REFRACTORY	TURKEY	NEW LINE
41 SISECAM RUSCAM UFA	2007	LINING INSTALLATION AND HEAT UP CONTAINER GLASS FURNACE REFRACTORY	RUSSIA	NEW LINE
ANADOLU CAM TOPKAPI FURNACE D(		DECONSTRUCTION ,REFRACTORY LINING		
42 SISECAM)	2006	INSTALLATION AND HEAT UP CONTAINER GLASS FURNACE REFRACTORY	TURKEY	COLD REPAIR
43 SISECAM BURSA YENİSEHIR FURNACE A	2006	LINING INSTALLATION AND HEAT UP SERVICES FLOAT GLASS FURNACE REFRACTORY	TURKEY	COLD REPAIR
TRAKYA CAM LULEBURGAZ TR1		DECONSTRUCTION , REFRACTORY LINING		
44 FURNACE(SISECAM)	2006	INSTALLATION, HEAT UP SERVICES CONTAINER GLASS FURNACE REFRACTORY	TURKEY	COLD REPAIR
ANADOLU CAM MERSIN FURNACE B(		DECONSTRUCTION, REFRACTORY LINING		
45 SISECAM)	2006	INSTALLATION AND HEAT- UP INSULATION (GLASSWOOL) FURNACE	TURKEY	COLD REPAIR
46 IZOCAM DILOVASI	2006	REFRACTORY LINING INSTALLATION INSULATION (GLASSWOOL) FURNACE	TURKEY	NEW LINE
47 IZOCAM TARSUS	2006	REFRACTORY LINING INSTALLATION	TURKEY	NEW LINE
48 MERSİN SODA SANAYİİ (SISECAM)	2005	LIME CHIMNEY LINING INSTALLATION CONTAINER GLASS FURNACE REFRACTORY	TURKEY	NEW LINE
ANADOLU CAM TOPKAPI FURNACE B(		DECONSTRUCTION ,REFRACTORY LINING		
49 SISECAM)	2005	INSTALLATION AND HEAT UP CONTAINER GLASS FURNACE REFRACTORY	TURKEY	COLD REPAIR
50 GUROK ARTCRAFT FURNACE B	2004	DECONSTRUCTION,REFRACTORY LINING INSTALLATION AND HEAT UP	TURKEY	COLD REPAIR
51 GUROKLAR MADEN SANAYİ	2002	TABLEWARE GLASS REFRACTORY LINING INSTALLATION AND HEAT UP	TURKEY	NEW LINE
52 MERSIN SODA SANAYİ(SISECAM)	2002	SODA LIME FURNACE REFRACTORY DECONSTRUCTION, REFRACTORY LINING INSTALLATION	TURKEY	COLD REPAIR
53 ISTANBUL CAM FABRIKASI	1998	LIGHTING GLASS FURNACE REFRACTORY LINING INSTALLATON	TURKEY	NEW LINE